



## **15 x10 Wheel Safety Advisory/Exchange Program**

Due to concerns about shortened fatigue life of a limited number of 15 x 10 wheels used on the RIGHT SIDE of late model pavement cars, Bassett Racing Wheel has announced a replacement program for these wheels.



### **PRODUCT AFFECTED**

**15 X 10 Wide-Five models** (all finishes) with a 4", 4.5" or 5" backspace built between January – August, 2006 used on the RIGHT SIDE of the race car.

### **DATE CODES/RANGE AFFECTED**

Locate the date stamp inside the back bell of the rim shell, approximately 4" to the left of the rim shell seam.

- No date code or hard to read are affected wheels
- Date code stamp range between 0106 – 0806.



**CEASE USE OF AFFECTED WHEELS ON THE RIGHT SIDE OF THE CAR IMMEDIATELY.**

### **CORRECTIVE ACTION**

Please take affected wheels to your nearest Bassett Wheel dealer or contact the factory directly at 888-888-7199 to arrange for exchange for new wheels date stamped 1006 or newer.

Bassett Racing Wheel apologizes for this issue and the disruption it causes to racers and our dealers. We are working diligently to alert users to this concern and make replacements available.

Sincerely,

Bassett Racing Wheel